

**ENVIRONMENTAL PERMITTING (ENGLAND AND WALES) REGULATIONS 2010****ADDRESS OF PERMITTED INSTALLATION:****ASDA PETROL FILLING STATION  
WALNEY ROAD BARROW-IN-  
FURNESS, CUMBRIA. LA14 5UG****NAME AND ADDRESS OF OPERATOR:**ASDA STORES LIMITED  
ASDA HOUSE  
SOUTHBANK, GREAT WILSON  
STREET, LEEDS. LS11 5AD

Person Spoken to	Mr Duncan Smith
Contact Phone Number	826011 Ext 261
The service station has <b><u>ONE storage tank.</u></b>	Yes
The service station is at <b><u>STAGE II vapour recovery.</u></b>	Yes
Have there been any <b><u>vapour leaks</u></b> and are they recorded in the <b><u>log book.</u></b> <i>Conditions 3 &amp; 34</i>	None recorded
Any instances of a <b><u>'Vapour Lock'</u></b> and are they recorded in the <b><u>log book.</u></b> <i>Conditions 5 &amp; 34</i>	None recorded
<b><u>Correct signage</u></b> around loading point "Connect vapour return line before off-loading" <i>Condition 13</i>	New signage with recent upgrade of facilities
<b><u>Loading points</u></b> secure. <i>Condition 19</i>	Yes, emergency call box bracken needs replacing.
<b><u>Pressure vacuum relief valves</u></b> shall be checked for correct functioning, including extraneous matter, seating and corrosion at least once every three years. <i>Condition 23</i>	Yes
<b><u>Petrol delivery and vapour recovery systems tested.</u></b> 1.Vapour containment integrity at least once every three years. 2. Effectiveness of the vapour recovery system at least once every three years. <i>Condition 28</i>	Stage 2 inspected 3/7/2014, next inspection 2/7/2017

<p>Check <b>Automatic Monitoring System</b>. Any faults noted. (Traffic light system on pump) <i>Condition 30</i></p>	<p>No faults recorded</p>
<p><b>Preventative maintenance</b> for all vapour recovery systems. <i>Condition 31</i></p>	
<p>The operator shall <b>maintain a log book</b> at the authorised premises incorporating details of all <b>maintenance, examination and testing, inventory checking, installation and repair work</b> carried out, along with details of <b>training</b> given to operating staff at the service station. The log book shall also detail any suspected vapour leak together with action taken to deal with any leak, <i>Conditions 3, 4, 5 and 34.</i></p>	<p>Log book kept up to date.</p>
<p><b><u>Inspection Notes.</u></b></p> <p>None.</p>	

Date: \_\_\_\_\_

Officer: \_\_\_\_\_